








**Eastbound Platform**











March/September 21



Images show the position of the shade provided by a standard bus shelter roof











**Eastbound Platform**

June 21



**Eastbound Platform**









December 21



Images show the position of the shade provided by a standard bus shelter roof












**Northbound Platform**

March/September 21



**Northbound Platform**







June 21



Images show the position of the shade provided by a standard bus shelter roof











**Northbound Platform**

December 21














**Southbound Platform**

March/September 21



**Southbound Platform**







June 21



Images show the position of the shade provided by a standard bus shelter roof

**Southbound Platform**










December 21



Images show the position of the shade provided by a standard bus shelter roof







**Westbound Platform**

March/September 21



**Westbound Platform**

June 21



**Westbound Platform**

December 21

